

## **City of Tacoma 2024 Annual Report**

**Q.61a Documentation of maintenance time frame exceedances that were beyond the Permittee's control. (S5.C.10.a.ii)**

### **Facility ID 6269283 Detention Tank at 1911 Dumas Circle**

Inspection noted missing control structure. Unable to reach a consensus on the type/size of orifice or control structure needed. Will attempt to install a control structure in 2025.

### **Facility ID 6262988 Pervious Pavement at 5110 Marine View Drive**

Pervious pavement failed water infiltration test. Unable to access pervious pavement with equipment due to eco blocks, which were placed to prevent homeless encampments. Will schedule to have eco blocks moved and pervious pavement maintained in 2025.